CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF	FILE - Gasoline in Sewer	DATE 11-5-86	
DEPARTMENT			

Subject - Lakes Country Building Products

On November 4, 1986 I received a call from the fire department indicating they had responded to Lakes Country Building Products, 820 N.W. By Pass on a complaint of gasoline odors in a portion of the building. A reading of 55% was achieved on the fire department explosion meter in a small room which had an open pipe in the floor. The pipe was closed off and another reading taken. This reading was 0%. The fire department asked that I check the city sewer serving this property. The results of the investigation are as follows:

Wye Map M-4

Manhole #10 - reading of 0% Manhole #9 - reading of 0%

I informed the fire department of these findings.

cc: Fire Department

Bob Corson

820 NW. BYPASS SIGNED Water Pollution Control Inspector III Surveillance & Enforcement

City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form
Date 2/2/90

Report From: Citizen Fire Dept Sewer Maintenance Other Occor Mar I	Received By: 5 5
Name pre Courted Har Address 820 De Mert Phone 862-5571 Directions (if needed)	By Pass Address 900 N. West By Procs Phone
	f: [] soil [] groundwater [] surface water what body? [] other SANSIBNI SELVEN.
Who to contact: DNR 417-883-4033 DNR 314-634-2436 EPA 913-236-3378 Fire Dept 864-1719 Police Dept 864-1719	☐ CU 831-8320 ☐ Chemtrec 800-424-9300 ☐ Street Dept ☐ DOT ☐ Health Dept ☐ NRC 312-790-5500
THE REAR	PE TWO WEEKS AGO OND NE TWO WEEKS AGO OND WAS SEWER GAS WE COUD WAS LEUS IN THE BUILDING WHOLES GOT COUD EMELLIT LESTADOM WHEN TRAP REPOSE P EXHAUST SAN TURNED ON WHILE OF THE INTERIOR
Action needed: TRUX WAShES PLIOT TO WEL A TANK DE WASHES PAO TANK DE WASHES PAO THAT IS NOT	TANKER THAT MORNING. GASOLNE TANKERS INTERIORS D'ING THEM HIS OBSERVED CLEANED THAT HAD CARRIED CLEANED THAT HAD CARRIED SED SOR WASHING YERSTER COVERED. IT IS TROUTARY WATER SEXL. THIS WAS NOT RING OUR INSPECTION.

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF / SWY	DATE 3-28-90
DEPARTMENT	
constant from	Lake County Hardware
of derel order.	Heavy soin had
cause runoff fro	m oil storage area
(sendited) in the rea	i of Trux property
to leave Trux prope	ut via south
front gate area	and run actors
habe Country parking I	It to storm sewar,
There was a visabligher	, raenbow on the
storm runoff and a	heavy order of dissel
8	720 NW BYPASS SE

TO: STEVE H	EIRO DATE_	Department of Public Works 830 Bnorwillo Springlield, Missouri 65802 (417) 864-1900
FROM: RAISY		
For your information		
For your comments	For your signature	
For your approval	As you requested	
Please call/see me on this	Prepare reply for ;	Tr/yan
Please take required action X	Please return	· signature
MESSAGE:	. Please file	
- CONTACT		
- AND DE	Bldg. R.	
DED HOUIS	5 -10	75.
- Jour	nomo	LX_
		75
		X-

February 2, 1990

Memo to File

This office received a call from Lake Country Hardware, 820 North West By-Pass concerning gasoline odors in their building. At 1:30 p.m. Maren Chandler and Steve Short tested the manhole etmosphere for L.E.L. in manholes 6, 9, and 8, wye map M-4. were O % L.E.L. We inspected the interior of the building with "Smitty" from Lake Country. Slight odors could be detected in the building all L.E.L. readings were O %. When the trap was removed from the sink, and the exhaust fan turned on in the production area restroom we could smell the gasoline odor, but not record a L.E.L. reading. We talked to the manager of Safety Kleen, Perry Harston, and inspected their operation. No problems were reported or observed. We also inspected the exterior of the Trum building. There we observed a covered washbay with a gasoline tanker parked in it. Also, next to the covered washbay on the northeast end of the building an uncovered concrete wash pad that appeared to be tributary to the sump of the covered washbay. Trux was in the process of washing out a transport tenker treiler that had contain egg products. We talked to Mr. Greg Dishman, Shop Foreman, who informed us Trux had washed out the gasoline tanker trailer that morning. Mr. Dishman stated there was no gasoline in the tanker, but they are cleaned out prior to welding on them for safety reasons.

It would appear the gasoline odor comes from the Trux washing operation. The Building Regulations Department should be contacted to determine if the sump in the covered wash area conforms to their code and if the outside wash area should be covered. This office should advise Trux of discharge limits and possible surcharge requirements.

Steve Short

WPCI

TRUX " NO ASI

med Often boutland go college purify go.

820 NW BYPASS